## Message Text

UNCLASSIFIED

PAGE 01 MADRID 07433 291013Z

17

ACTION FBOE-00

INFO OCT-01 EUR-12 ISO-00 SSO-00 /013 W

----- 045714

O 290840Z SEP 76

FM AMEMBASSY MADRID

TO SECSTATE WASHDC IMMEDIATE 7346

**UNCLAS MADRID 7433** 

E.O.11652: N/A TAGS: BLD

SUBJECT: EMERGENCY REPAIRS TO CHANCERY ROOF

- 1. FOLLOWING HEAVY RAINS LAST WEEKEND, THE CHANCERY ROOF BEGAN LEAKING IN AT LEAST 4 PLACES CAUSING WATER DAMAGE TO SCATTERED AREAS ON THE 7TH FLOOR OF THE CHANCERY. INSPECTION REVEALS THE ROOF MUST BE COMPLETELY REDONE ON AN EMERGENCY BASIS.
- 2. PRESENT ROOFING MATERIAL IS CONCRETE BASE COVERED WITH LAYER OF SAND TOPPED BY CATALONIAN RED CERAMIC TITLE, APPROXIMATELY 4 INCH SQUARES.
- 3. POSSIBILITIES FOR RECOVERING ROOF ARE:
  A) COVER EXISTING TITLE WITH 1/2 HOT ASPHALT,
  COVERED BY 4 COATS OF ROOFING PAPER, FOLLOWING BY ANOTHER
  1/2 INCH HOT ASPHALT, COVERED BY LOOSE GRAVEL.
  GUARANTEED FOR 3 YEARS. ESTIMATED COST: \$4,500.
  B) COVER EXISTING TITLE ROOF WITH 1/2 INCH HOT
  ASPHALT, COVERED WITH FOUR LAYERS ROOFING PAPER, THEN A
  LAYER OF EXPANDED METAL (CHECKEN) WIRE, WITH
  1/2 INCH CONCRETE TOPPING COVERED BY CATALONIAN
  TITLE TO MATCH EXISTING SURFACE. ESTIMATED COST:
  \$9,000 WE WILL ASK FOR 10 YEAR GUARANTEE.
- 4. THE EMBASSY PREFERS PROPOSAL B AND WILL PROCEED ON THAT BASIS.

UNCLASSIFIED

UNCLASSIFIED

PAGE 02 MADRID 07433 291013Z

5. THE EMBASSY WAS AWARE OF THE NEED TO EVENTUALLY

RECOVER THE CHANCERY ROOF AND INCLUDED \$9,000 FOR THIS PURPOSE IN THE SUMMARY FOGURES FOR ITS 77 BUILDINGS BUDGET. THE EMBASSY WILL LET THE CONTRACT AS SOON AS BIDS AND SPECIFICATIONS ARE AVAILABLE. AND ASKS THAT THE \$9,000 BE INCLUDED IN THE POST M&R ALLOTTMENT WHEN ISSUED. STABLER

UNCLASSIFIED

NNN

## Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

**Current Classification: UNCLASSIFIED** 

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 29 SEP 1976 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a

Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976MADRI

Document Number: 1976MADRID07433
Document Source: CORE
Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D760366-1434

From: MADRID

Handling Restrictions: n/a

Image Path:

Legacy Key: link1976/newtext/t1976098/aaaaagkr.tel

Line Count: 68

Locator: TEXT ON-LINE, ON MICROFILM Office: ACTION FBOE Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: n/a Previous Handling Restrictions: n/a Reference: n/a Review Action: RELEASED, APPROVED Review Authority: greeneet

Review Comment: n/a Review Content Flags: Review Date: 23 APR 2004

**Review Event:** 

Review Exemptions: n/a
Review History: RELEASED <23 APR 2004 by MaustMC>; APPROVED <28 DEC 2004 by greeneet>

**Review Markings:** 

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MÁY 2006

**Review Media Identifier:** Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: EMERGENCY REPAIRS TO CHANCERY ROOF

TAGS: ABLD, US, SP To: STATE

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006